

L Number	Hits	Search Text	DB	Time stamp
1	1853	fulcrum near6 (constrict\$4 narrow\$4 constring\$4 reduc\$5 contract\$5 compress\$4 compact\$4 tighten\$4 shrink\$4)	USPAT; US-PGPUB; EPO; JPO	2004/09/05 13:30
2	3	fulcrum near4 constriction	USPAT; US-PGPUB; EPO; JPO	2004/09/05 13:33
3	166	(fulcrum lever) near6 constrict\$3	USPAT; US-PGPUB; EPO; JPO	2004/09/05 13:37
4	136	((fulcrum lever) near6 constrict\$3) and (force pressure load balance)	USPAT; US-PGPUB; EPO; JPO	2004/09/05 13:34
5	135	((fulcrum lever) near6 constrict\$3) and (force pressure)	USPAT; US-PGPUB; EPO; JPO	2004/09/05 13:34
6	8	(((fulcrum lever) near6 constrict\$3) and (force pressure)) and 73/\$.ccls.	USPAT; US-PGPUB; EPO; JPO	2004/09/05 13:34
7	53	(fulcrum lever) near6 constriction	USPAT; US-PGPUB; EPO; JPO	2004/09/05 13:44
8	513302	(pressure force load) near4 (measur\$4 detect\$4 sens\$4 indicat\$4 monitor\$4 cell transducer gage gauge scale balance weigh)	USPAT; US-PGPUB; EPO; JPO	2004/09/05 13:45
9	575761	(pressure force load) near4 (measur\$4 detect\$4 sens\$4 indicat\$4 monitor\$4 cell transducer gage gauge scale balance weigh\$3)	USPAT; US-PGPUB; EPO; JPO	2004/09/05 13:49
10	9866	((pressure force load) near4 (measur\$4 detect\$4 sens\$4 indicat\$4 monitor\$4 cell transducer gage gauge scale balance weigh)) and (fulcrum lever).clm.	USPAT; US-PGPUB; EPO; JPO	2004/09/05 13:50
11	99636	((pressure force load) near4 (measur\$4 detect\$4 sens\$4 indicat\$4 monitor\$4 cell transducer gage gauge scale balance weigh\$3)).clm.	USPAT; US-PGPUB; EPO; JPO	2004/09/05 13:49
12	31245	((pressure force load) near4 (measur\$4 detect\$4 sens\$4 indicat\$4 monitor\$4 cell transducer gage gauge scale balance weigh\$3)).ti.	USPAT; US-PGPUB; EPO; JPO	2004/09/05 13:49
13	3650	(((pressure force load) near4 (measur\$4 detect\$4 sens\$4 indicat\$4 monitor\$4 cell transducer gage gauge scale balance weigh\$3)).clm.) and (fulcrum lever).clm.	USPAT; US-PGPUB; EPO; JPO	2004/09/05 13:51
14	243	(((pressure force load) near4 (measur\$4 detect\$4 sens\$4 indicat\$4 monitor\$4 cell transducer gage gauge scale balance weigh\$3)).ti.) and (fulcrum lever).clm.	USPAT; US-PGPUB; EPO; JPO	2004/09/05 13:51
15	2	(((pressure force load) near4 (measur\$4 detect\$4 sens\$4 indicat\$4 monitor\$4 cell transducer gage gauge scale balance weigh\$3)).ti.) and (fulcrum lever).clm.) and constriction.clm.	USPAT; US-PGPUB; EPO; JPO	2004/09/05 13:51